



AWS 2221
July 20, 2018

Doug Anderson
County of Mendocino
841 Low Gap Road, Ukiah, CA

**RE: Hazardous Materials Inspection Report
Mendocino County Yokayo Center – Exterior and Roof
747 South State St, Ukiah, CA**

Dear Mr. Anderson,

Air & Water SCIENCES (AWS) is pleased to submit the following Hazardous Materials Inspection Report for the site referenced above. This report includes the procedures and methodologies followed and analytical laboratory data from our inspection performed on July 11, 2018.

AWS was requested to collect samples of suspected asbestos containing materials and suspected lead containing painted surfaces from the portion of the Yokayo Center roof scheduled to be demolished in the near future. The analytical data is presented in this report.

AWS appreciates the opportunity to perform these services for you and we look forward to working with you in the future. Please know that if you have questions or comments regarding the information in this report at any time or if we can be of further assistance, we can be reached at (707) 769-2289.

Respectfully submitted,

Air & Water SCIENCES

A handwritten signature in blue ink, appearing to read "Chip Prokop".



Chip Prokop, PE, CIEC, CAC 08-4420
Principal



Scope of Work

- Collect samples of suspect asbestos containing materials from the portion of the roof scheduled to be demolished in the near future.
- Collect XRF analyses for lead in paint contents from painted exterior portions of the building that may be included in the upcoming renovations in the near future.
- Provide a written report summarizing the results of the inspection.

Background

The Mendocino County Yokayo Center located at 747 South State Street is a single-story county owned building that houses the social services for the county. The County of Mendocino is planning to demolish the exterior roof overhang on the western side of the building sometime in the near future. Its original construction date is unknown. AWS was requested to do a building inspection prior to work being performed on the building.

ASBESTOS INSPECTION

Survey Results

The pre-renovation asbestos inspection was performed by Trent Williams, a California Site Surveillance Technician (CSST 18-6204), under the direction of Chip Prokop (CAC 08-4420). The ACM inspection was performed in areas that were accessible to the inspector at the time of the site visit. A total of ten (10) bulk samples were collected from four (4) homogeneous building materials identified in the interior and exterior of the building. The laboratory provided a total of nineteen (19) analytical results based upon the number of samples that were analyzed.

The materials that were tested as suspected asbestos containing materials (ACM) are included in Table 1. AWS collected samples of suspect asbestos containing materials including:

- **Black roofing tar with white paint**
- **Rolled shingle roofing with tar**
- Tan wall concrete
- Brown exterior masonry

The bulk samples were analyzed by EMSL Analytical Inc. in San Leandro, California using the methods prescribed in Method 40 CFR, Ch. 1, Part 763, Subpart F, Appendix A in the Code of

Federal Register in analyzing bulk samples. This laboratory participates in the NVLAP and ELAP quality assurance programs for PLM and is accredited by the National Institute of Standards and Technology (NIST) and the California Department of Health Services Environmental Laboratory Accreditation Program for Bulk Asbestos Analyses (Title 22 of California Code of Regulations [CCR], Section 66261.24), number 101048-3. The suspect asbestos bulk samples were collected and submitted to the laboratory using established chain-of-custody procedures.

Sampling Results

AWS was requested to collect samples of suspected asbestos containing materials in areas that are planned to be demolished in the near future. **Analytical results of the samples performed by polarized light microscopy (PLM) indicated that the black roofing tar and the black roofing shingles are both 5% to 6% Chrysotile Asbestos.**

Important Note:

Additional ACM may be present on site in inaccessible or concealed spaces. These spaces include, but are not limited to, crawlspaces, pipe chases, spaces between wall/ceiling/door/floor cavities, beneath foundation pads, etc.

When future activities, including maintenance, renovation, or demolition activities, make these areas accessible, AWS recommends that a thorough assessment of these spaces be conducted to identify and confirm the presence or absence of additional ACM. Until this is done, all previously unidentified materials must be treated as Presumed Asbestos Containing Materials (PACM) in accordance with 29 CFR 1926.1101 and 1910.1001.

LEAD INSPECTION

Mr. Trent Williams, CDPH certified Lead Sampling Technician #29837, performed the inspection on July 11, 2018. A discussion of recommendations and regulatory considerations are provided later in this report.

Lead-In-Paint XRF Survey Procedures

The sampling strategy employed was performed as outlined in Title 17, California Code of Regulations, Division 1, Chapter 8 and in accordance with those survey procedures listed in the "Guidelines for the Evaluation and Control of Lead Based Paint Hazards in Housing", June 1995,

by the U.S. Department of Housing and Urban Development (HUD). Our investigation included the collection of readings on similar painted surfaces (not every component in every room as dictated by HUD guidelines).

Prior to data collection, painted/coated surfaces were categorized into distinct areas of homogeneity, substrate material, building material, and/or distinct paint type. After the items have been identified, a representative reading of the painted/coated surface is collected. Because painted/coated surfaces have compositional variability due to one or more paint layers, it is possible to obtain different readings for samples from the same homogeneous area. Therefore, a homogeneous area with at least one XRF reading of 1.0 mg/cm^2 or greater will result in the entire homogenous material, substrate, and/or distinct paint type being designated as lead-based paint.

Each XRF reading along with the location, component, substrate, color, and condition of the painted/coated surface is included in the XRF readings table located at the end of this report.

Sample Analysis

The XRF testing was performed in accordance with the aforementioned criteria, using a ThermoFisher Scientific, Niton Portable XRF Analyzer. Exposure times are internally determined by the instrument and are based on a number of factors including lead content, substrate and source strength. The instrument is calibrated to the manufacturer's specifications and was periodically verified against known lead standards produced by the National Institute of Standards and Testing.

HUD defines action level as the hazard level for which a corrective response action will be required. Currently, the most widely used action level for lead-based paint (LBP) is 1.0 mg/cm^2 (as measured by an XRF) established by HUD and adopted by the U.S. Environmental Protection Agency. The action level is 5000 parts per million (ppm) or 0.5% by weight when collected paint chip samples are analyzed using atomic absorption spectroscopy (AAS).

HUD guidelines consider XRF findings of 1.0 mg/cm^2 or greater as lead-based paint which may be a potential hazard when disturbed. It is extremely important to understand that XRF readings, which have a value of 0.0 mg/cm^2 , do not necessarily mean there is "no lead present" however are below the minimum detection limit of the instrument.

Testing Results

During the inspection, a total of fourteen (14) readings were collected from the interior and exterior surfaces of the building. Analytical results revealed the following:

- **Lead Based Paint was identified in the following painted surfaces:**
 - The grey exterior wooden walls.
 - The beige exterior plaster walls.

Regulatory Considerations/Recommendations

Based on the XRF readings the disturbance materials identified with lead-based paint would be subject to the U.S. Environmental Protection Agency (EPA) Lead Renovation, Repair and Painting Program. Both lead based painted material and material with any lead in paint content (lead containing paint) are subject to the California Occupational Safety and Health Administration (Cal-OSHA) regulations for lead containing paint for workers who may chip or remove paint. The following section of the report is a summary of the Cal/OSHA lead regulation.

Construction Work Standards

At present, there are no state or federal laws dealing with mandatory abatement following the identification of lead containing or lead based paints prior to disturbance. However, in 1993 OSHA promulgated legislation (29 CFR 1926.62 and 8 CCR 1532.1) entitled "Lead Exposure in the Construction Industry" which deals with worker exposure to lead.

It should be noted that aside from the HUD definition of lead-based paint (1.0 mg/cm^2), OSHA regulates worker protection and work practices on building components containing any detectable amounts of lead. Therefore, components determined to contain less than 1.0 mg/cm^2 may still be subject to OSHA regulations, if these materials are to be disturbed. This standard essentially states that work, involving components containing any amount of lead must follow certain guidelines.

These guidelines include but are not limited to training, personal protective equipment, and specific work practices whenever workers disturb lead in any concentration because the disturbance may result in airborne exposures over action or permissible exposure limits. This legislation requires that any task that may potentially expose workers to any concentration of lead be monitored to determine workers' eight-hour time weighted average (TWA) exposure to

lead. Prior to conduction of activities that may generate a lead exposure, such workers must be properly fitted with respiratory protection and protective clothing until personal eight-hour TWA results reveal exposures within acceptable levels.

Any proposed renovation, which may involve the removal of building materials with lead based or lead containing painted surfaces, should include provisions to minimize the potential for airborne release of lead contaminated dust. It is recommended, as a minimum, that demolition of building materials which have lead based and/or lead containing paints be conducted with the materials kept in a wetted state and removed in sections, as feasible, to reduce the potential for airborne lead emissions.

Limitations

The interpretation of the preliminary findings identified in this report is based upon our professional experience and qualifications. The field investigation and laboratory results are limited to only those areas, which were exposed and/or physically accessible to the inspector as outlined by the scope of work and/or as directed by the client. The study is also limited to the information provided by the client at the time of the inspection. Quantities listed within this report are estimations and should be confirmed by an abatement contractor prior to renovation and/or demolition work is performed.

Although polarized light microscopy (PLM) is the prescribed analysis for bulk sample evaluation, PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bounded materials. Quantitative inspection using transmission electron microscopy (TEM) is currently the only method that can be used to determine if this material can be considered or treated as non-ACM. However, TEM is not considered cost effective in a limited asbestos survey and is done only upon client request. Please let AWS know if this additional analysis is desired.

AWS is not qualified to present medical advice. If any present or future health issues arise, it is recommended that the findings in this report be presented to a qualified medical professional for review. Additionally, AWS is not a law firm, and therefore, makes no representations regarding any potential liability of any person or entity for site conditions.

SECTION 2
BAAQMD/NESHAPS NOTIFICATION INFORMATION
747 South State St, Ukiah, CA


Inspection Date	7/11/2018
Laboratory	EMSL in San Leandro, CA
Number of Samples	10 PLM
Date Analyzed	7/15/2018
Inspector Certification	Trent Williams (CSST)
Training Provider	M&C Environmental
Certificate No.	18-6204
Expiration Date	May 16, 2019

TESTED SUSPECTED ASBESTOS CONTAINING MATERIALS

(Bold type = Asbestos Containing Materials (> 0.1%))

Material (Classification)	Location of Material (Sample No.'s)	Condition	Friable Yes/No	Quantity, NESHAP Category, (OSHA Class)	Results Recommendations
Black roofing tar with white paint (M)	Interior of roof overhang (2221-01, 2221-02)	Good	No	100 sq. ft. NESHAP Category 1 (OSHA Class 2)	Paint = ND Tar = ND Roofing = 5% - 6% Chrysotile Remove under Class 2 roofing conditions, dispose of as asbestos waste, Non-Friable Category I material
Black rolled shingle roofing with tar (M)	Interior of roof overhang (2221-03, 2221-04, 2221-05, 2221-06)	Good	No	3200 sq. ft. NESHAP Category 1 (OSHA Class 2)	Shingle = ND Tar = ND Roofing = 5% - 6% Chrysotile Remove under Class 2 roofing conditions, dispose of as asbestos waste, Non-Friable Category I material

Material (Classification)	Location of Material (Sample No.'s)	Condition	Friable Yes/No	Quantity, NESHAP Category, (OSHA Class)	Results Recommendations
Tan concrete wall (M)	Interior and exterior of roof overhang (2221-07, 2221-08)	NA	NA	NA	Non-Detect
Brown exterior masonry (M)	Exterior pillars at entrances (2221-09, 2221-10)	NA	NA	NA	Non-Detect
NA = Not Applicable, ND = Non-Detect, NYD = not yet determined, SF = Square Feet, S = Surfacing, M = Miscellaneous, PACM = Presumed Asbestos-Containing Material, RACM = Regulated Asbestos- Containing Material, ACCM = Asbestos-Containing Construction Material, Cat. I = Category I, Non- friable Asbestos-Containing Material, Cat. II= Category II, Non-friable Asbestos-Containing Material, * Inseparable, Positive By Association, Unclassified = disturbance of ACCM does not have an OSHA Class designation					



KEY

- = EXTERIOR LEAD BASED PAINT BELOW OVERHANG
- = ASBESTOS SAMPLE LOCATION

Lead Based Paint Sample Results

Site Location:	747 South State St., Ukiah, CA
Building:	Mendocino County Yokayo Center
Inspector:	Trent Williams

Job #: AWS 2221

Date of Inspection: 7/11/2018

Location	Component	Substrate	Wall	Paint Condition	Color	RESULTS	Analytical Result (mg/cm ²)
Calibration						Negative	< LOD
Calibration						Positive	3
Calibration						Positive	1.1
Calibration						Positive	1.5
Calibration						Negative	0.6
Calibration						Negative	0.29
ATTIC	WALL	PLASTER	A	INTACT	BROWN	Negative	NLD
ATTIC	WALL	WOOD	A	INTACT	DARK GREY	Negative	NLD
ATTIC	WALL	WOOD	A	INTACT	BROWN	Negative	NLD
ATTIC	ROOF	METAL	A	INTACT	GREY	Negative	NLD
OUTSIDE	ROOF	WOOD	A	INTACT	GREY	Negative	NLD
OUTSIDE	ROOF	PLASTER	A	INTACT	TAN	Negative	NLD
OUTSIDE	ROOF	PLASTER	A	INTACT	TAN	Negative	NLD
OUTSIDE	COLUMN	METAL	A	INTACT	BLUE	Negative	NLD
OUTSIDE	COLUMN	CONCRETE	A	INTACT	BROWN	Negative	NLD
OUTSIDE	COLUMN	WOOD	A	PEELING	RED	Negative	NLD
OUTSIDE	WALL	WOOD	A	INTACT	GREY	Positive	1.7
OUTSIDE	WALL	PLASTER	A	CRACKED	BEIGE	Negative	NLD
OUTSIDE	WALL	PLASTER	A	CRACKED	BEIGE	Positive	2
OUTSIDE	WALL	PLASTER	A	CRACKED	BEIGE	Negative	NLD
Calibration						Positive	3.4
Calibration						Positive	2
Calibration						Positive	2
Calibration						Positive	1.5
Calibration						Positive	1.8
Calibration						Positive	1.6
	= Calibration						
NLD	= No Lead Detected						
LCP	= Lead Containing Paint Detected						
LBP	= Lead Based Paint Detected						



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 091815367

Customer ID: IDAS26

Customer PO: AWS 2221

Project ID:

Attention: Chip Prokop
Air & Water Sciences
625 2nd Street
Suite 210
Petaluma, CA 94952

Project: MC YOKAYO CTR - AWS 2221

Phone: (707) 478-1383

Fax: (707) 658-2031

Received Date: 07/13/2018 9:45 AM

Analysis Date: 07/15/2018

Collected Date: 07/11/2018

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
2221-01-Silver Paint <small>091815367-0001</small>	BLACK ROOFING TAR WITH WHITE PAINT	Silver Non-Fibrous Homogeneous		90% Matrix 10% Non-fibrous (Other)	None Detected
2221-01-Roofing <small>091815367-0001A</small>	BLACK ROOFING TAR WITH WHITE PAINT	Black Fibrous Homogeneous	15% Cellulose	70% Matrix 10% Non-fibrous (Other)	5% Chrysotile
2221-02-Silver Paint <small>091815367-0002</small>	BLACK ROOFING TAR WITH WHITE PAINT	Silver Non-Fibrous Homogeneous		90% Matrix 10% Non-fibrous (Other)	None Detected
2221-02-Roofing <small>091815367-0002A</small>	BLACK ROOFING TAR WITH WHITE PAINT	Black Fibrous Homogeneous	15% Cellulose	70% Matrix 9% Non-fibrous (Other)	6% Chrysotile
2221-02-Tar <small>091815367-0002B</small>	BLACK ROOFING TAR WITH WHITE PAINT	Black Non-Fibrous Homogeneous		95% Matrix 5% Non-fibrous (Other)	None Detected
2221-03-Shingle <small>091815367-0003</small>	ROLLED SHINGLE ROOFING WITH TAR	Gray/Black Non-Fibrous Homogeneous		25% Quartz 60% Matrix 15% Non-fibrous (Other)	None Detected
2221-03-Tar <small>091815367-0003A</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Non-Fibrous Homogeneous		95% Matrix 5% Non-fibrous (Other)	None Detected
2221-03-Roofing <small>091815367-0003B</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Fibrous Homogeneous	15% Cellulose	70% Matrix 9% Non-fibrous (Other)	6% Chrysotile
2221-04-Shingle <small>091815367-0004</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Non-Fibrous Homogeneous		20% Quartz 60% Matrix 20% Non-fibrous (Other)	None Detected
2221-04-Roofing <small>091815367-0004A</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Fibrous Homogeneous	15% Cellulose	70% Matrix 10% Non-fibrous (Other)	5% Chrysotile
2221-04-Tar <small>091815367-0004B</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Non-Fibrous Homogeneous		95% Matrix 5% Non-fibrous (Other)	None Detected
2221-05-Shingle <small>091815367-0005</small>	ROLLED SHINGLE ROOFING WITH TAR	Gray/Black Non-Fibrous Homogeneous		30% Quartz 60% Matrix 10% Non-fibrous (Other)	None Detected
2221-05-Tar <small>091815367-0005A</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Non-Fibrous Homogeneous		10% Quartz 80% Matrix 10% Non-fibrous (Other)	None Detected
2221-06-Shingle <small>091815367-0006</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Non-Fibrous Homogeneous		25% Quartz 70% Matrix 5% Non-fibrous (Other)	None Detected
2221-06-Tar <small>091815367-0006A</small>	ROLLED SHINGLE ROOFING WITH TAR	Black Non-Fibrous Homogeneous		95% Matrix 5% Non-fibrous (Other)	None Detected
2221-07 <small>091815367-0007</small>	TAN CONCRETE WALL	Gray Non-Fibrous Homogeneous		30% Quartz 60% Ca Carbonate 10% Non-fibrous (Other)	None Detected

Initial report from: 07/15/2018 12:21:49



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 091815367

Customer ID: IDAS26

Customer PO: AWS 2221

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
2221-08 <i>091815367-0008</i>	TAN CONCRETE WALL	Gray Non-Fibrous Homogeneous		30% Quartz 60% Ca Carbonate 10% Non-fibrous (Other)	None Detected
2221-09 <i>091815367-0009</i>	BROWN EXTERIOR MAROOMY	Gray Non-Fibrous Homogeneous		30% Quartz 60% Ca Carbonate 10% Non-fibrous (Other)	None Detected
2221-10 <i>091815367-0010</i>	BROWN EXTERIOR MAROOMY	Gray Non-Fibrous Homogeneous		30% Quartz 60% Ca Carbonate 10% Non-fibrous (Other)	None Detected

Analyst(s)

Oscar Merino (19)

Matthew Batongbacal
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc San Leandro, CA NVLAP Lab Code 101048-3, WA C884

Initial report from: 07/15/2018 12:21:49



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

#091815367

EMSL ANALYTICAL, INC.
464 MCCORMICK STREET
SAN LEANDRO, CA 94577

PHONE: (510) 895-3675

FAX: (510) 230-3537

Company : AIR & WATER SCIENCES		EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 625 2 ND STREET, SUITE 210		Third Party Billing requires written authorization from third party	
City: PETALUMA	State/Province: CA	Zip/Postal Code: 94952	Country: USA
Report To (Name): CHIP PROKOP		Fax #: 707-658-2031 cell #707-478-1383	
Telephone #: 707-769-2289		Email Address: cprokop@awsciences.com/lesley@awsci....	
Project Name/Number: MC Yokengo Chr, AWS-2221			
Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email		Purchase Order:	U.S. State Samples Taken:
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input checked="" type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
*For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.			
PCM - Air <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA PLM - Bulk (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NIOSH 9002 (<1%)		TEM - Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 TEM - Bulk <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 TEM - Water: EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	
		TEM - Dust <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) Soil/Rock/Vermiculite <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) Other: <input type="checkbox"/>	
<input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group			
Samplers Name: Trent Williams		Samplers Signature: [Signature]	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
2221-01	Black roofing tar with white paint	1	7/11/18
2221-02	"	1	↓
2221-03	Redded single roofing with tar	2	
2221-04	"	2	
2221-05	"	2	
2221-06	"	2	
2221-07	tan concrete wall	3	
2221-08	"	3	
Client Sample # (s):		Total # of Samples:	
Relinquished (Client): [Signature]		Date: 7/11/18	Time: 1:30 pm
Received (Lab): [Signature]		Date: 7/13/18	Time: 9:45 am EMEX (C)
Comments/Special Instructions:			

0 9 1 8 1 5 3 6 7

Page 2 Of 2